

Etisalat Mesh Extender Firmware Release Note

Version	Date	Description
0.01.00.02250	2021-02-25	MP2 FW release
0.01.00.01070	2021-01-07	MP1 FW release
0.01.04080	2021-04-08	
0.01.04019	2021-04-19	

Version: 0.01.04190

Date: 2021-04-19

Feature Added / Modification / Improvement:

- Fine tune MESH and AP mode GUI menus
- Fix Wi-Fi LED off issue
- Reduce LED blink time when wired backhaul pairing
- Fix soft reset LED behavior
- Update new LED value table

Version: 0.01.04080

Date: 2021-04-08

Feature Added / Modification / Improvement:

- Add AP mode support and GUI menus
- New rule about TR69 CR port and path
- Add speedtest feature
- Fine tune LED behavior according to new requirement
- Change default SSID format
- Add signature into FW

Version: 0.01.00.02250

Date: 2021-02-25

Feature Added / Modification / Improvement:

- Support CE/FCC + High/Normal Power Tables
- Support Power Table/DFS setting via TR69 and sync from HomeBox
- Change default Power Table to CE/High
- Fine tune some TR098 nodes
- Fine tune LED color
- Fix some wrong LED behavior
- Split 24G/5G SSID default/GUI setting
- Support "192.168.1.x/mesh" for accessing the Mesh GUI
- Support 24G/5G dual Wi-Fi uplink
- Upgrade Wi-Fi driver to 17.10.157.2803

Bug Fix:

- M002 M006 M012

Known Bugs & Limitation:

- Support Firmware upgrade from HomeBox
- Support Group WPS feature with HomeBox (Group WPS for standalone mode is okay now)

Version: 0.01.00.01070

Date: 2021-01-07

Feature Added / Modification / Improvement:

- Support Onboarding with HomeBox/Mesh Extender Controller via Ethernet/WPS
- Support Wireless/Wired Backhaul
- Support Standalone Mode with other normal HGW
- Support GUI for Standalone mode
- Support Mesh controller and agent roles
- Support TR69 per Mesh Extender
- Support Firmware upgrade via ACS server and Mesh Extender GUI
- Support GUI redirect to Controller
- Upgrade Broadcom BSP to 5.04L02GA and Wi-Fi driver to 17.10.157.2802

Bug Fix:

Known Bugs & Limitation:

- Support Firmware upgrade from HomeBox
- Support Group WPS feature with HomeBox(Group WPS for standalone mode is okay now)
- Regulation power table for CE/FCC is not ready yet
- 50% of the TR69 nodes is ready now